
ZM10 - Strain relief connectors

This strain relief secures the two, USB-type, connectors used in AXIS P1244, P1264, F1004 and F1004 Pinhole. It may also be used together with AXIS FA3105L, FA4115, P1254 and P1275 in some applications.

In harsh environments, the strain reliefs may be secured with 2.4mm (0.1") cable ties. (In most applications, cable ties are not needed.)




The strain reliefs come in sets of 16 pcs.



Clamp it over the connectors. Use one/two cable ties, if needed.

Order by using this link: ZM10 - Set of 16 pcs strain relief Connectors


The parts are intended for indoor use.





www.ZebraMount.com zebra@ZebraMount.com

ZM10 - Strain relief connectors





www.ZebraMount.com zebra@ZebraMount.com

20191120